

RELEASE NOTES

MACKIE TT24 SOFTWARE UPDATE • JUNE 18, 2007

Version 1.5
Build 85

These release notes describe changes and upgrades that have been made in the TT24 software since Version 1.3 Build 68.

IMPORTANT: *Carefully read and follow the firmware instructions found at the link below or you will lose your snapshots and other saved data!*

http://www.mackie.com/products/tt24/pdf/TT24_Install_Upgrade.pdf

INSTALLATION

New software releases can be downloaded from Mackie's web site by going to the TT24 Product section and clicking "Downloads" or by following the link below.

<http://www.mackie.com/products/tt24/software.html>

If you don't know the software version you are currently using, you can check your software version and build number by pressing the "HELP" button on the console, or by clicking Menu > About in the TT Control PC application.

Please download the following files to update your TT24:

1. TT Control PC Application Setup (v1.5 Build 85)
2. TT Firmware/Software Installation/Upgrade Instructions (TT24_Install_Upgrade.pdf)
3. TT24 Owner's Manual Addendum Version 1.5 Update (TT24_OM_Add_15.pdf)

MANUALS

The TT24 Quick-Start Guide and TT24 Owner's Manual are posted on the web site as PDF downloads.

<http://www.mackie.com/products/tt24/#DOCUMENTS>

Adobe Acrobat Reader is available from Adobe's web site to read the PDF documents.

<http://www.adobe.com>

RELEASE NOTES FOR VERSION 1.5 BUILD 85

FIXED OR UPDATED SINCE VERSION 1.3 BUILD 68

1. Added Channel Naming feature (see manual addendum for details: TT24_OM_Add_15.pdf).
2. Added Tap Delay feature for setting the delay time for the Mono Delay, Stereo Delay, and Ping Pong effects (see manual addendum for details).
3. Added DS3232 support (see manual addendum for details).
4. Added Console Linking support (see manual addendum for details).
5. Added OPT•24T ADAT Expansion Card support (see manual addendum for details).
6. Fixed issue where copy/pasting between banks with different DSP was not working.
7. Fixed issue where snapshots created without a UFXII would not recall properly when a UFXII was installed and vice-versa.
8. Fixed issue where main outputs would drop out when DSP was assigned to groups.
9. Fixed issue where adjusting matrix delay in distance in TT Control had no effect on delay time. Only the time parameter is now directly adjustable.
10. Fixed graphics issue where internal GEQ sliders were labeled incorrectly in the TT control software.



MACKIE.

Part No. SW0203 Rev. D 06/07
©2007 LOUD Technologies Inc.
All rights reserved.
www.mackie.com