

RELEASE NOTES

MACKIE TT24 SOFTWARE UPDATE • APRIL 13, 2006

Version 1.3
Build 68

These release notes describe changes and upgrades that have been made in the TT24 software since Version 1.2 Build 60.

IMPORTANT: *Carefully read and follow the firmware instructions found at the link below or you will lose your snapshots and other saved data!*

http://www.mackie.com/products/tt24/pdf/TT24_FirmwareUpgrade.pdf

MANUALS

The TT24 Quick-Start Guide and TT24 Owner's Manual are posted on the web site as PDF downloads.

<http://www.mackie.com/products/tt24/#documents>

Adobe Acrobat Reader is available from Adobe's web site to read the PDF documents.

<http://www.adobe.com>

SOFTWARE INSTALLATION

New software releases can be downloaded from Mackie's web site by going to the TT24 Product section and clicking "Downloads" or by following the link below.

<http://www.mackie.com/products/tt24/#downloads>

If you don't know the software version you are currently using, you can check your software version and build number by pressing the "HELP" button on the console, or by clicking Menu > About in the TT Control PC application.

Please download the following files to update your TT24:

1. TT Firmware (1.3 Build 68)
2. TT Firmware Installation Instructions
3. TT Control PC App (1.3 Build 68)
4. TT Control Installation Instructions

RELEASE NOTES FOR VERSION 1.3 BUILD 68

FIXED OR UPDATED SINCE VERSION 1.3 BUILD 60

1. Enable copy and paste buttons to function on the internal graphic EQs. They can now be copied from Left to Right to Center.
2. Added Expansion window to touch screen and software to display configuration information and controls for expansion cards.
3. Added new "Expansion Card Options..." under the Main Menu drop-down in the TT Control PC software for updating the firmware on the expansion cards.
4. The AFL mode is now working correctly when recalling snapshots with/to linked channels.
5. Fixed issue where an AFL soloed stereo aux did not properly send the stereo image to the monitor bus.
6. Fixed issue where internal graphic EQs would not attenuate at all the incorrect frequencies.
7. Fixed console shortcut CTRL+METERS to open large meters screen on TT Control software.
8. Fixed issue with assigning matrix to internal FX via touch screen.
9. Fixed issue with adjusting the EQ on both the software and console simultaneously.
10. Mute group assignments are now properly stored in the snapshot.
11. Comp/EQ order for Groups and Aux sends is now properly stored in the snapshot.
12. Comp Knee and In/Out toggle buttons now function on TT Control L, R, and C/M overview.
13. Fixed issue where aux linking was not remembered properly (linked or unlinked) on bootup and/or snapshot recall.
14. Fixed miscellaneous GUI issues related to Matrix.
15. Fixed issue where EQ can get stuck in a disabled state when loading snapshots and/or presets.
16. Fixed issue where oscillation can occur when swapping the Comp and EQ order on an Aux send.



MACKIE®

Part No. SW0203 Rev. A3 04/06
©2006 LOUD Technologies Inc.
All rights reserved.
www.mackie.com